


# How to change COM"X" into COM"Y"

( Using change COM 5 into COM 3 as an example )

**Note:** In most cases, there is only 4 default setting COM interfaces in the test program and the POS machine, namely COM1-COM4 (shown as below); and a USB interface guest was inserted after the host, sometimes a randomly generated COM ports will exceed COM4, so need to be forced to change the computer COM port.



## Concrete steps:

- 1、Connect the USB interface of POS display with computer host.
- 2、Right click on the “computer” – “properties”–“Hardware”-“Device Manager”,shown as below:



- 3、Right click on the “USB Serial Port (COM5)”——“properties”
- 4、Click “Port Settings”
- 5、Click “Advanced” Dialog box, shown as below:




## 6、Choose COM Port Number:COM3



## 7、Pull off the data line from host computer,and plug again,shown as below:



## 8、Select test program corresponding to the COM3 port to be tested, as the following diagram



9、 Then, under the premise of driver installation, using test procedure for testing:

